

DATE 1041Z 31 OCT 64

S E C R E T

TO : DIRECTOR

FROM : [REDACTED]

25X1A

1	Conn	9
2	"	10
3	DEP	11
4	cc	12
5	OFF	13
6	RECH	14
7	/	15
8	/	16

ROUTINE

ACTION:

INFO :

TOR: 1222Z 31 OCT 64

OSIA 1-20 E IN 55372

TO 25X1A

INFO [REDACTED]

CITE [REDACTED]

0372 25X1A  
25X1A  
25X1A

25X1A

HEREWITH [REDACTED] READOUTS FOR MSN NO C224C

OCT 31, 1964. BW 100 PERCENT EFFECTIVE. NO SYS 12 OR 13 ACTIVITY  
NOTED.

PRE TAKE OFF:

0225Z BELOW 60M, BELOW 40M, EGT 325 OR LESS, RPM 75 PER CENT,  
80 KIAS OR LESS, INVERTER NO 1 ON, AC GEN OUT, AUTO PILOT  
DISENGAGED.

0225.5Z SAME EXCEPT A OK

0226Z SAME AS 0225Z

0227Z SAME AS 0225Z

0227.5Z SAME AS 0225Z

0228Z SAME AS 0225Z

REASON FOR ABOVE PROBABLY OXYGEN PRI ON FIRST CHIRP.

0229.5Z TAKE OFF:

BELLOW 60M, BELOW 40M, EGT 500-325 DEG C. RPM 75 PERCENT,  
INVERTER 1 ON, AC GEN ON. AUTO PILOT DISENGAGED.